

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
Victor Ketellapper
Phone 800-227-8917
http://www.epa.gov/region08



CONSENT FOR ACCESS TO PROPERTY

Name: Isidro Javier Vasquez (or current property owner)

Location of Property: 4445 Cook St

I consent to officers, employees, and authorized representatives of the United States Environmental Protection Agency (EPA) entering and having continued access to the above referenced property for the purpose of taking samples of soil on the Site.

I realize that these actions are undertaken pursuant to EPA's response and enforcement responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or Superfund), 42 U.S.C. § 9601 et seq.

Printed Name

720) X619001 -303-373-5617


Phone Number

Signature

Date

2017

VB-4445-CK-02 A VB-4445-CK-03 *



Section	Grid	Points.
٥١	141	81
٥Z	lolo	13 /
60	44	91
_	151/3	5,033

1450 **I** 1455 A 1500 *

Dyar / Marie

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-4445-CK-01 Client Project ID: 213001.01 Date Collected: 11/11/05 Date Received: 11/11/05

Lab Work Order: 05-8518 Lab Sample ID: 05-8518-01

Sample Matrix: Soil

METALS

Method: SW6010 Prep Method: SW3050

Date Prepared: 11/23/05 Lab File ID: 112805PM Dilution Factor: Method Blank: MB-8706 Date Analyzed: 11/28/05 Lab Fraction ID: 05-8518-01A **CAS Number** Analytes Result LQL Units Arsenic 7440-38-2 U 4.0 mg/Kg Lead 7439-92-1 56 5.8 mg/Kg

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample exceeded analytical holding time

I - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL)

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-4445-CK-02

Client Project ID: 213001.01 Date Collected: 11/11/05 Date Received: 11/11/05

Lab Work Order: 05-8518 Lab Sample ID: 05-8518-02

Sample Matrix: Soil

METALS

Method: SW6010 Prep Method: SW3050

Date Prepared: 11/23/05 Date Analyzed: 11/28/05	Lab File ID: 112805PM Method Blank: MB-8706	Dilution Factor: 1 Lab Fraction 1D: 05-8518-02A		
Analytes	CAS Number	Result	LQL	Units
Arsenic	7440-38-2	4.1	4.0	mg/Kg
Lead	7439-92-1	66	5.9	mg/Kg

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL)

Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 11/29/05

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-4445-CK-03

Client Project ID: 213001.01

Lab Work Order: 05-8518 Lab Sample 1D: 05-8518-03

.

Sample Matrix: Soil

Date Collected: 11/11/05 Date Received: 11/11/05

METALS

Method: SW6010 Prep Method: SW3050

Date Prepared: 11/23/05 Lab File ID: 112805PM Dilution Factor: 1 Date Analyzed: 11/28/05 Method Blank: MB-8706 Lab Fraction ID: 05-8518-03A Analytes CAS Number Result LQL Units Arsenic 7440-38-2 4.9 4.1 mg/Kg 7439-92-1 100 Lead 6.0 mg/Kg

> Y\Q Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL)

Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 11/29/05



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

999 18TH STREET- SUITE 300 DENVER, CO 80202-2466 Phone 800-227-8917

http://www.epa.gov/region08

Ref: 8EPR-SR

December 7, 2005

ISIDRO JAVIER VASQUEZ 4039 JASON ST DENVER CO 80211

RE: 4445 COOK ST

Dear Owner,

As part of the VB/I-70 Superfund Site investigation, we recently took soil samples at your property to find out if there is too much lead or arsenic in your yard. The results show that your property does not require a cleanup. The levels of both lead and arsenic are below our cleanup levels. The soil sampling results for your property are as follows:

ADDRESS: 4445 COOK ST_

EPA Cleanup Levels

Lead

74 parts per million (ppm)

above 400 ppm

Arsenic

5 ppm

above 70 ppm

This means that your property is not considered by EPA to be part of the VB/I-70 Superfund Site. EPA does not believe that further measures are necessary. You and your family are not at significant risk from arsenic through ordinary contact with soil in your yard while playing, working, gardening, etc. Please note that there may be small areas in your yard, particularly near your house, that may have higher levels of lead due to peeling, external lead-based paint. EPA encourages all owners of older properties to take reasonable precautions regarding lead-based paint.

For further information, please feel free to contact EPA Community Involvement Coordinators Jennifer Chergo at (303) 312-6601 or Patricia Courtney at (303) 312-6631.

Sincerely,

Victor Ketellapper

Remedial Project Manager

The Environmental Protection Agency, Region 8